TRERICE

TR890 Series (TR891, TR892, TR893, TR894) Digital Controller

Instruction Manual

Thank you for purchasing a Trerice product.

Please check that the delivered product is the correct item you ordered.

Please do not begin operating this product before you read this instruction manual thoroughly and understand its contents.

Notice: Please ensure that this instruction manual is given to the final user of the instrument.

Preface: This instruction manual is meant for those who will be involved in the wiring, installation, operation and routine maintenance of the TR890 series (TR891, TR892, TR893 and TR894). It describes matters to be attended to in handling the TR890 series, how to install it, its wiring, its functions and operating procedures. Keep this manual at the work site while handling the instrument and follow the guidance provided herein

Contents

1. Safety Rules2	5-7. Explanation of Screen Group 1 and Setting14~18
2. Introduction	(1) Setting of Keylock
2-1. Check before Use	(2) Setting of Output
2-2. Handling Instruction4	(3) Setting of Event
3. Installation and Wiring	(4) Heater Current Monitor Screen16
3-1. Installation Site4	(5) Setting of Heater Break/Loop Alarm16
3-2, Mounting	(6) Setting of Analog Output Type16
3-3. External Dimensions and Panel Cutout 5	(7) Setting of Communication
3-4. Wiring 6	(8) Setting of Control Output Characteristic17
3-5. Terminal Layout7	(9) Setting of Soft Start Time
3-6. Terminal Arrangement Table	(10) Setting of SV Limiter17
4. Names and Functions of Parts on Front Panel	(11) Setting of PV Bias Value
5. Explanation of Screens and Setting 9~18	(12) Setting of PV Filter Time
5-1. Parameter Flow	(13) Setting of Measuring Range Code18
5-2. Display upon Power-ON	(14) Setting of Temperature Unit
5-3. How to Change Screens	(15) Setting of Input Scaling
(1) How to Change Screens in Screen Group 0	5-8. Table of Measuring Range Codes
(2) How to Change Screen Group 0 to/from Screen Group 110	6. Explanation of Functions19~20
(3) How to Change Screens in Screen Group 110	6-1. Events19
(4) How to Change Set Values (Data)10	6-2. Setting of Event Standby Action
5-4. Before Starting Up11	6-3. Alarm Actions Diagrams
(1) Checking of Wiring11	6-4. P.I.D
(2) Application of Operating Power11	6-5. Manual Reset20
(3) Setting of Measuring Range11	6-6. Lower Limit and Higher Limit Setting Limiters20
(4) Setting of Control11	6-7. Proportional Cycling Time
(5) Setting of Control Output Characteristics	6-8. Auto Return Function
(6) Setting of Event Type11	6-9. Control Output Characteristics
(7) Setting of Analog Output11	6-10. Soft Start
(8) Note on Initialization Following Data Change11	7. Maintenance and Troubleshooting
5-5. Procedure of Setting in Screen Group 011	7-1. Procedure of Maintenance Replacement and Matters to Be
(1) Setting of Target Set Value	Attended to21
(2) Manual Setting of Control Output11	7-2. Causes of Trouble and Troubleshooting21
(3) AT (Auto Tuning)12	7-3. Error Codes, Causes and Remedies22
(4) Setting of Event Set Value	8. Record of Parameter Setting
(5) Set Value Bias	9. Specifications
5-6. Explanation of Screen Group 0 and Setting	

Trerice • 12950 W. Eight Mile Road • Oak Park, Michigan 48237 Tel: 888-TRERICE • Fax: 248-399-7246 • www.trerice.com

1. Safety Rules

For matters regarding safety, potential damage to equipment and/or facilities, additional instructions and notes are indicated by the following headings.

MARNING: This heading indicates hazardous conditions that could cause injury or death of personnel

unless extreme caution is exercised.

A CAUTION: This heading indicates hazardous conditions that could cause damage to equipment and/or

facilities unless extreme caution is exercised.

NOTE: This heading indicates additional instructions and/or notes.

The mark \bigoplus represents a protective conductor terminal. Make sure to ground it properly.

- ⚠ WARNING -

The SR90 series is designed for controlling temperature, humidity and other physical quantities of general industrial equipment. Avoid using it for control of devices upon which human life is dependent. When used, adequate and effective safety measures must be taken. No warranty is valid in the case of an accident arising from the use of this product without having taken such safety measures.

-∆ WARNING -

- For using this instrument, house it in a control box or the like to prevent terminals from coming into contact with personnel.
- Do not draw out the instrument out from its case. Do not let your hand or any conductive body into the case. It may lead to serious injury or death due to an electric shock.
- Make sure to ground protective conductor terminals.

- ▲ CAUTION -

To avoid damage to connected equipment, facilities or the TR890 itself due to a fault of the product, safety measures must be taken before usage, such as the installation of a fuse, an overheating protection device and the like. No warranty is valid in the case of an accident arising from the use of this product without such safety measures.

- The alert mark ⚠ on the plate affixed to the instrument: On the terminal nameplate affixed to the case of this instrument, the alert mark ⚠ is printed. This is to warn you of the risk of electric shock which may result if the charger is touched while being energized.
- As a means to turn the power off, a switch or a breaker should be installed in the external power circuit to be connected to the power terminal of the instrument. Fix the switch or the breaker adjacently to the instrument in a position which allows it to be operated with ease, with an indication that it is a means of turning the power off. Use a switch or a breaker which meets IEC947 requirements.
- Fuse: Since the instrument does not have a built-in fuse, do not forget to install a fuse in the power circuit to be connected to the power terminal. A fuse should be positioned between a switch or a breaker and the instrument and mounted on the L side of the power terminal.
 Fuse rating/characteristics: 250 VAC 0.5 A/medium lagged or lagged type. Use a fuse which meets IEC127 requirements.
- Voltage/current of a load to be connected to the output terminal and the alarm terminal should be within a rated range. Otherwise, the temperature will rise to reduce the life of the product and/or to result in problems with the product. For rated voltage/current, see 9. Specifications.
 The output terminal should be connected with a device which meets the requirements of IEC1010.
- A voltage/current different from that of the input specification should not be applied to the input terminal. It may reduce the life of the product and/or result in problems with the product. For rated voltage/current, see 9.
 Specifications.

In the case of voltage or current input, the input terminal should be connected to a device which meets IEC1010 requirements.

The instrument is provided with a draft hole for heat discharge. Take care to prevent metal and other foreign matter from entering into it. Failure to do so may result in trouble with the instrument or may even cause a fire.

- Do not block the draft hole or allow dust or the like to stick to it. A rise in temperature or insulation failure may result in a reduction of the life of the product and/or problems with it or may cause a fire.
 - For spaces between installed instruments, refer to 3-3. External Dimensions and Panel Cutout.
- It should be noted that repeated tolerance tests against voltage, noise, surge, etc., may lead to deterioration of the instrument.
- Users are prohibited from remodeling the product or using it in a prohibited way.

2. Introduction

2-1. Check before Use


This product has been fully inspected for quality assurance prior to shipment. Nevertheless, you are requested to make sure that there is no error, damage or shortage of delivered items by checking the model codes and the external view of the product and the number of accessories.

Confirmation of Model Codes


Check the model codes affixed to the case of the product to ascertain if the respective codes designate what was specified when you ordered it, referring to the following code table:

TR890 series is based on 3 types of selectable codes TR891 · TR892 · TR93 and TR894. Please refer to the following example of model codes.


Example of TR891 model type codes:



Example of TR892 model type codes:



Example of TR893, TR894 model type codes:



② Accessories

This instruction manual 1 copy
The Communication interface instruction manual (in case optional communication function is added)
Unit seals
Current detector for heater break alarm (CT) (in case optional heater break alarm function is added)
For 30A: Model CTL-6-S
For 50A: Model CTL-12-S36-8

1 copy
I sheet
I pc.

NOTE: For any problem with the product, shortage of accessories or request for information, please contact our agent or our sales office in your neighborhood.

2-2. Handling Instruction

- ① Do not operate the keys on the front panel with a hard or sharply pointed object. Operate the keys only by softly touching them by your fingertips.
- ② When cleaning the instrument, wipe it gently with a dry cloth. Never use solvent such as a thinner.

3. Installation and Wiring

3-1. Installation Site (environmental conditions)

- ▲ CAUTION -

This instrument should not be used in any of the places mentioned below. Selection of these places may result in trouble with the instrument, damage to it or even a fire.

- 1 Where flammable gas, corrosive gas, oil mist and particles that can deteriorate electrical insulation are generated or abundant.
- ② Where the temperature is below -10°C or above 50°C.
- 3 Where the relative humidity is above 90%RH or below the dew point.
- 4 Where highly intense vibration or impact is generated or transferred.
- (§) Near high voltage power lines or where inductive interference can affect the operation of the instrument.
- 6 Where the instrument is exposed to dew drops or direct sunlight.
- Where the height is above 2000 m.
- ® Outdoors.

NOTE: The environmental conditions belong to the installation category II of IEC664 and the degree of pollution is 2.

3-2. Mounting


- ⚠ CAUTION -

For safety's sake and to protect the functionality of the product, do not draw out its body from the case. If it needs to be drawn out for replacement or repair, call our agent or our sales office in your neighborhood.

- ① Cut a hole for mounting the controller in the panel by referring to the cutout drawing in Section 3-3.
- ② The panel thickness should be $1.0 \sim 4.0$ mm.
- 3 As the instrument is provided with pawls for fixing, just press it firmly from the front of the panel.
- The TR890 series instrument is designed in a panel-mounting mode. Never use it without mounting on the panel.

3-3. External Dimensions and Panel Cutout 111 100 TR891 Panel cutout drawing 48 In the case of installat without leaving space between instruments N=The number of instruments Unit: mm TR892 111 11, Panel cutout drawing 100 \$0 20 a0 20 a0 **3**0 **3**0 °C TR893 111 11, 100 Panel cutout drawing 130 or more °C sv 96 WE 0/F (ENT) Unil: mm SHIMADEN TR894 111 100 11 48 Panel cutout drawing (48 × N−3) ½ C 130 0 In the case of installation without leaving space between instruments 96 68 N=The number of instruments Unit: mm

External dimensions of current detectors (CT) of heater break alarm




3-4. Wiring


In the wiring operation, close attention should be paid to the following:

-∕N WARNING


- Make sure to disconnect this product from any power source during the wiring operation to prevent an electric shock.
- Be certain that the protective conductor terminal ((\(\beta\)) is properly grounded. Otherwise, an electric shock may result.
- To prevent an electric shock, do not touch wired terminals and other charged elements while they are being energized.
 - ① In the wiring operation, follow the terminal layout shown in Section 3-5 and the terminal arrangement in Section 3-6 and make sure to carry out the correct wiring process.
 - ② Use a press-fit terminal which fits an M3.5 screw and has a width of 7 mm or less.
 - 3 In the case of thermocouple input, use a compensating conductor compatible with the selected type of thermocouple.
 - ④ In the case of R.T.D. input, the resistance of a single lead wire must be 5Ω or less and the three wires must have the same resistance.
 - (§) The input signal wire must not be accommodated with a high-voltage power cable in the same conduit or duct.
 - 6 Shield wiring (single point grounding) is effective against static induction noise.
 - Twisting the input wires at short and equal intervals is effective against electromagnetic induction noise.
 - (a) In wiring for power supply, use a wire or cable whose performance is equal to or higher than the 600V vinyl insulated wire having a sectional area of 1 mm² or larger.
 - The wire for grounding must have a sectional area of 2 mm² or larger and must be grounded at a grounding resistance of 100Ω or less.
 - © Clamp the screws of terminals firmly. Clamping torque: 1.0 N • m (10 kgf • cm)
 - fill the instrument appears to be easily affected by power supply noise, use a noise filter to prevent malfunctioning. Mount the noise filter on the grounded panel and make the wire connection between the noise filter output and the power line terminals of the controller as short as possible.



② Connection of current detector (CT)
Insert a load line through the hole of the noise filter
meant for the controller. With this wire, connect the
secondary side terminal of CT to the CT input terminal
of the TR890 series controller.







3-6. Terminal Arrangement Table

	Name of terminal		Terminal	No.
Name of terminal	Description/Code		TR892	TR893 • 94
Power supply	100-240V AC/24V AC: L, 24V DC: + 100-240V AC/24V AC: N, 24V DC: –	6 7	8 9	11 12
Protective conductor	(b)	8	10	13
Input	R.T.D.: A, thermocouple/voltage/current: + R.T.D.: B, thermocouple/voltage/current: - R.T.D.: B	2 4 5	4 6 7	7 9 10
Control output 1	Contact: NO, SSR drive voltage/Voltage/Current: + Contact: NO, SSR drive voltage/Voltage/Current: -	9 10	11 12	14 15
Control output 2 (option)	Contact: NO, SSR drive voltage/Voltage/Current: + Contact: NO, SSR drive voltage/Voltage/Current: -	11	13 14	16 17
Event output (option)	COM EVI EV2	13 14 15	19 20 21	18 19 20
Heater break (option)	CT input	11-12	17-18	5-6
Analog output (option)	+	11 12	15 16	1 2
Communication (option)	RS-232C: SD, RS-485: + RS-232C: RD, RS-485: - SG RS-485: + RS-485: -	1 11 12	2 3 1	2 3 1
Set value bias (option)		11-12	1-2	3-4

NOTE

With thermocouple/voltage/ current input, shorting across B and B terminal will cause an error.

NOTE:

The optional functions of the SR90 are subject to the following conditions:

TR891:

Only one of control output 2, heater break alarm, analog output, communication and set value bias is selectable.


TR892:

Communication and set value bias are not selectable simultaneously.

TR893/94:

Communication and analog output, or communication and set value bias are not selectable simultaneously. Simultaneous selection of analog output and set value bias is possible, though.

4. Names and Functions of Parts on Front Panel




Name	Function
① Measured value (PV) display:	 Present measured value (PV) is displayed on the screen group 0, basic screen and output display screens (OUT1 and OUT2). (red) Type of parameter is shown on each parameter screen.
② Target set value (SV) display:	 Target set value (SV) is displayed on the basic screen of the screen group 0. (green) Present output value is displayed by % on control output monitor screens (OUT1, OUT2) of the screen group 0. Selected item and set value are displayed on each parameter screen.
③ Action display lamps:	 (1) Control output indicators: OUT1 and OUT2 (option) (green) OUT1 lights when output turns ON and goes out when it turns OFF during contact or SSR drive voltage output. The brightness changes in proportion to output increase/decrease during current or voltage output. OUT2 functions only if the option is added. Event output indicators: EV1/EV2 (option) (orange) Light when assigned events (including heater break/loop alarm) turn ON if event option is added. Auto tuning action indicator: AT (green) Flashes when ON is selected by key on the AT action selection screen and AT is executed by ky, and goes out when AT terminates automatically or is released. Manual control output action indicator: MAN (green) Flashes when manual control output is selected on control output display screens (OUT1, OUT2); remains unlit during automatic control output. Set value bias/communication indicator: SB/COM (option) (green) Lights when optional set value bias function is added and at the time of shorting across SB terminal (set value bias in action). Lights when optional communication function is added and COM mode is selected. Goes out when Local is selected for communication mode.
Operating keys:	 (1)

5. Explanation of Screens and Setting


5-1. Parameter Flow

Outline of Parameter Flow displayed below. Set parameter according to the explanation of each setting screen.



5-2. Display upon Power-ON

When power is applied, initial screens upon power-ON are displayed successively, each for about 1 second. Then the basic screen is displayed.




5-3. How to Change Screens

Screen group 0 (the group of screens for setting primarily by the end user)

Screen group 1 (the group of screens for setting primarily by the manufacturer and equipment manufacturers)

(1) How to Change Screens in Screen Group 0

Every time the PARA key is pressed, the screen moves to the next and the 0-0 basic screen returns when it is pressed on the last screen.




(2) How to Change Screen Group 0 to/from Screen Group 1

Pressing the key continuously for 3 seconds on the basic screen of the screen group 0 calls the 1-0 initial screen of the screen group 1 onto display. Also by pressing the key continuously on the 1-0 initial screen of screen group 1 calls the basic screen of screen group 0.



(3) How to Change Screens in Screen Group 1

Starting from the 1-0 initial screen of the screen group 1, every time the key is pressed, the next screen appears and the 1-0 initial screen returns when it is pressed on the last screen. By pressing the key while pressing the key in the screen group 1, you can go back to the preceding screen. When the key is pressed while the key is being pressed on the 1-0 initial screen, the last screen of this group, i.e., the 1-52 input scaling decimal point position setting screen appears on the display.



(4) How to Change Set Values (Data)

To change data on a screen which is called by pressing the key, use the for key, and register the changed data by pressing the key key.

5-4. Before Starting Up

To begin with, check the wiring and set the items listed below by the setting methods of the screen groups. (Factory-set items and items already set by equipment manufacturers need not be set here.)

- (1) Checking of Wiring: Check that the wiring to connected terminals is carried out properly. Erroneous wiring will result in burnout.
- (2) Application of Operating Power: Apply operating power. The controller is energized and the data display and other lamps light.
- (3) Setting of Measuring Range: Call the 1-48 measuring range code screen of the screen group 1 and select a code from the measuring range codes. For current, voltage or mV input, lower/higher limit values and the position of decimal point should be set. (Depending on a selected code, selection on the 1-49, 1-50 or 1-51 screen will be required.)
- (4) Setting of Control: In the case of ON-OFF (two-position) action, call the 1-2 output 1 proportional band setting screen of the mode 1 screen group and select OFF and register it. Follow the same procedure for output 2 if the option is added. Omit this setting in the case of AT.
- (5) Setting of Control Output Characteristics: Call the 1-42 control output characteristic setting screen of the screen group 1 and select either RA or DA correspondingly to output characteristic specification as shown in the table.
- (6) Setting of Event Type: If the optional event function is added, call the 1-20 event alarm type code setting screen of the screen group I and select and register a code.
- (7) Setting of Analog Output: If the optional analog output function is added, call the 1-31 analog output type setting screen of the screen group 1 and select one from the setting range and register it.
- (8) Note on Initialization Following Data Change: When the code of measuring range, type of event or type of analog output is changed, a set value is initialized and resetting is required.

5-5. Procedure of Setting in Screen Group 0

In the following section 5-6, the flow of setting screens is explained in the next section, "Explanation of Screen Group 0 and Setting." In this section, the procedure of setting is described.


Key operation:

Use the key to call the next screen. On each setting screen, use the for very key for selection and the (ENT) key for registration. Nevertheless, in case the value of manual control output is changed on the output monitor screen, the (ENT) key need not be pressed.

- (1) Setting of Target Set Value (SV)
 - ① To set a target set value (SV), press the (A) or (T) key on the 0-0 basic screen. When either of the keys is pressed continuously, the decimal point of the rightmost digit flashes and the numerical value keeps increasing or decreasing. When it reaches a target set value, press the (EN) key to register.
 - ② Once it reaches the target set value, the digit stops flashing. (Setting of a target set value is not possible while auto tuning (AT) is in execution. AT should be relieved for setting.)

Example: 500.0°C is to be set as a target set value.

0-0 basic screen




- (2) Manual Setting of Control Output
 - 1) Switching between automatic output and manual output on output monitor screen (OUT1 and OUT2) and setting: To switch auto to manual and vice versa, press the (END) key for 3 seconds continuously on the output 1 or output 2 screen. Upon turning to manual, the MAN lamp flashes and it remains unlighted during automatic output.

To set a target value, press the over the output monitor screen to keep the numerical value increasing or decreasing until a target value is reached.

- To release manual output, press the END key again for 3 seconds continuously, and automatic output returns.
- 1 If the output mode of either output 1 or output 2 is changed to manual, the output mode of the other is also changed to manual. Also, if changed to auto, the output of the other will be changed to auto as well.
- In case the output of output 1 is at 100.0%, \$\sigma 999\$ is displayed on the output 1 screen and the decimal point of \$\sigma\$ flashes.
 In case the output of output 2 is at 100.0%, \$\sigma 999\$ is displayed on the output 2 screen and the decimal point of \$\sigma\$ flashes.
- 10 In case output is of contact or SSR drive voltage and OFF is set for proportional band (P), the value of output will be 0.0% or 100.0%.
- In case output is of voltage or current and OFF is set for proportional band (P), the value of output will be the lower limit value or the higher limit value of a set limiter.

While auto tuning (AT) is in execution, switching to manual output is not possible. It should be done after releasing AT.

0-1 Output monitor screen



- 2) Supplemtary explanation of using the manual adjustment output
 - Monitor screens (OUT1 and OUT2) and automatic/manual output:
 - ① When automatic output is changed to manual, output is put in a balanceless/bumpless action and the value of output right before the change is displayed. Changing from manual to auto also causes bumpless action but not if the PV value is outside the proportional band.
 - ② If power supply is shut off and power is applied again, control output continues to be in auto or manual at the time when power supply is shut off.
 - Note: Although a change to another screen in the manual mode is possible, it should be noted that control output is manual in this case. Flashing of the MAN monitor LED indicates that the manual mode is ON.


(3) AT (Auto Tuning)

AT is the function of automatically processing and setting P.I.D., the parameters of P.I.D. control. Processing time differs depending on the details of control.

1) Execution of AT

Pressing the or key on the 0-3 AT action control screen changes F displayed on the bottom to and the decimal point of the rightmost digit flashes. Then press the key. The AT lamp flashes and AT starts. When AT is executed, ON/OFF action of output in response to rising and falling of the measured value from the target set value is repeated several times to store PID values internally and AT ends. At the same time control using stored PID values begins and the AT lamp goes out.


0-3 AT action control screen



2) Halfway releasing of AT

To stop AT in the middle of execution, select $\Box FF$ by using the $\textcircled{\blacksquare}$ or $\textcircled{\blacksquare}$ key on the AT action control screen and by pressing the $\textcircled{\blacksquare}$ key, releases the AT and the decimal point and the AT lamp stops flashing.

0-3 AT action control screen



- 3) In the following conditions, AT is unable to be executed:
 ① Control output is in manual. (The AT screen not displayed.)
 - ② Scaleover of PV (measured value). (The AT screen not displayed.)
 - Scaleover of PV (measured value). (The AT screen not displayed.)
 OFF is selected for proportional band (P) of output 1. (The AT screen not displayed.)
 - 1 Lock No. 2 or 3 selected on the keylock screen.
- 4) If the following occur while AT is in execution, AT will be released:
 - The output value has been at 0% or 100% continuously for 200 minutes.
 - ② Scaleover of PV value
- 5) AT works as follows in the instrument of two-output specifications:
 - ① RA characteristic: PID constants are common to OUT1 and OUT2.
 - ② DA characteristic: AT is executed only for OUT1 and while AT is in execution, output of OUT2 is at 0% or the lower limiter value of output limiter.

(4) Setting of Event Set Value

Before a value is set, an event type should be set as described in the following paragraph, 1) Event type setting. When an event type code is changed, however, all the set values (data) concerning the event are initialized.

1) Event type (alarm type) setting

Call the 1-20 event 1 type code setting screen of the screen group 1 and select one from the type codes Hd, Ld, od, id, HA and LA by pressing the and keys. Then register it by the key.

There are the following 6 event type (alarm type) codes: $\mathcal{H}_{\mathcal{O}}$: Higher limit deviation, $\mathcal{L}_{\mathcal{O}}$: Lower limit deviation, $\mathcal{L}_{\mathcal{O}}$: Outside higher/lower limit deviations, $\mathcal{L}_{\mathcal{O}}$: Within higher/lower limit deviations, $\mathcal{H}_{\mathcal{O}}$: Higher limit absolute value, $\mathcal{L}_{\mathcal{O}}$: Lower limit absolute value. A selected code is displayed and an action point is to be set for the selected event type (alarm type). ($\mathcal{O}_{\mathcal{F}}\mathcal{F}$: None, $\mathcal{S}_{\mathcal{O}}$: Scaleover, and $\mathcal{H}_{\mathcal{O}}$: Heater break/loop alarm are screen display only.)

2) Setting of event value


The 0-4 event 1 set value setting screen or the 0-5 event 2 set value setting screen will set. It will be on display when either of the previous 6 types of event is selected.

Set the aimed value by pressing the or key on screen. When the key is pressed to register the set event value, the decimal point stops flashing.

Setting ranges: Higher limit deviation value or lower limit value: -1999 ~ 2000 units

Outside or within higher/lower limit deviation values: 0 ~ 2000 units

Higher limit absolute value or lower limit absolute value: Within measuring range
(No event value can be set while AT (auto tuning) is in execution. Set after releasing AT.)



3) Changing the event value

To change the value, pressing the or the key causes the decimal point to flash and the value will change. Press the key to set your aimed value, the decimal points will stop flashing.

(5) Set Value Bias

1) Set value bias

As an optional function, additional setting of another target set value is possible.

It is set as a set value bias which indicates a deviation from the target set value.

For instance, when 20°C has been set as the target set and you want to set another set value at 30°C, set the set value bias at +10°C.

The set value bias becomes effective when the SB terminals are closed.

When the SB terminals are open, the target set value becomes effective.

This function is used conveniently to switch a target value between "summer and winter"/"day and night" and the like.

2) Setting of set value bias

In case the optional set value bias function is added, press the or key on the 0-6 screen to set a numerical value of set value bias and register the value by pressing the key. The decimal point stops flashing.

The set value remains effective while the SB terminals are shorted and is added to the target set value. When a set value bias is set, the SB/COM lamp lights.

Setting range: -1999~5000 units

(4) Standby mode (STBY)

1) What is standby mode?

This instrument supports standby mode (STBY), which stops the control operation temporarily. Switching to/from execution/STBY can be set on the 0-3 STBY action control screen. When STBY is assigned to DI (external input) on the 1-35 DI mode setting screen, the setting on the screen 0-3 cannot be performed, as DI setting is preferred.

- ① During STBY, the decimal point of the lowermost digit on the PV display flashes.
- ② The output value is 0% during STBY.
- ③ When STBY is selected, AT (auto tuning) is stopped.
- When STBY is selected in manual control, manual control is released.
- (5) If the power supply is shut off in STBY and power is applied again, STBY is still selected.
- ® During STBY, event output can be set at enable or disable.
- If set, event standby action can be executed when the instrument is switched from standby (STBY ON) to execution (STBY OFF).

2) Event at standby

Event can be set enable or disable on the 1-20 event at STBY setting screen.

oFF

Event output disabled (except for status).

Event output enabled when the specified condition is satisfied.

Note that event isn't output in case control mode is selected for event standby action

(Code 4 on the screen 1-23 or 1-26).

. If 5ϖ or HB is assigned to event type, the event is output even if it is in STBY.

3) PV display at standby

PV display at standby can be set on the 1-57 PV display at standby setting screen.

PH

During STBY, PV value is displayed on the basic screen and the output monitoring


screen.

5*L b y*

During STBY, the characters "5Lb9" are displayed instead of the PV value on the basic

screen and the output monitoring screen.

6. Explanation of Screen Group and Setting



(2) Setting of Output	
1-2 Output 1 propotional band (P) setting screen	1-10 Output 1 proportional cycling time setting screen
/P Initial value: 3.0%	□□□ Initial value: Contact output: 30 seconds
<i>∃□</i> Setting range: OFF, 0.1 ~ 999.9%	SSR drive voltage output: 3 seconds Setting range: 1 ~ 120 seconds.
Basically setting of this item is not necessary for the execution of auto tuning. For proportional band, refer to Section 6-4 (1). To change to ON-OFF (two-position) action, select OFF.	Proportional cycling time of control output 1 is set. The screen is not displayed for voltage or current output. For proportional cycling time, refer to Section 6-7
1-3 Output 1 hysteresis setting screen	1-11 Output 2 (OUT2) proportional band (P) setting screen
Initial value: 20 units Setting range: 1 ~ 999 units	P ≥ Initial value: 3.0%
Set the "Hysteresis" of ON-OFF action. This screen is displayed only when OFF is selected for "P=OFF" on the preceding 1-2	Setting range: OFF, 0.1 ~ 999.9% The same as the output I (OUT1) proportional hand (P) setting
screen.	screen. This screen is displayed when the optional output 2 function is added.
1-4 Uutput 1 integral time setting screen	1-12 Uutput 2 hysteresis setting screen
/ Initial value: 120 seconds Sctting range: OFF, 1 ~ 6000 seconds	ロータ ロ Initial value: 20 units Setting range: 1 ~ 999 units
Basically, setting of this item is not necessary when auto tuning is executed.	"Hysteresis" for ON-OFF action is set. This screen is displayed only when P=OFF is selected on the
For integral time, refer to Section 6-4 (2). This screen is not displayed when P=OFF is selected.	preceding 1-11 screen.
	1-13 Output 2 integral time setting screen
1-5 ↓ Output 1 derivative time setting screen.	/ _ Initial value: 120 seconds Setting range: OFF, 1 ~ 6000 seconds
Initial value: 30 seconds Setting range: OFF, 1 ~ 3600 seconds Basically, setting of this item is not necessary when auto tuning is	The same as the output 1 integral time setting sereen.
executed.	
For integral time, refer to Section 6-4 (3). This screen is not displayed when P=OFF is selected.	1-14 ↓ Output 2 derivative time setting screen. G ☐ ☐ Initial value: 30 seconds
	Setting range: OFF, 1 ~ 3600 seconds The same as the output 1 derivative time setting screen.
1-6 Uutput 1 manual reset setting screen	©
Initial value: 0.0% or -50.0% when the controller is of 2 output specifications.	1-15 Uutput deadband setting screen
Setting range: -50.0% ~ 50.0% A value for offset correction is set when OFF is selected for I	db 2 Initial value: 0 units Setting range: −1999 ~ 5000 units
(P action or PD action). This screen is not displayed when P=OFF is selected.	The position of the action output 2 against the action position of output 1 is set.
Refer to Section 6-5.	For dead band, refer to section 6-9.
1-7 Output 1 target value function setting screen	1-16 Output 2 target value function setting screen
SF Initial value: 0.40	5F 2 Initial value: 0.40
Setting range: OFF, 0.01 ~ 1.00 A value to be used to suppress overshooting or undershooting in	Setting range: OFF, 0.01 ~ 1.00 The same as the output 1 target value function setting screen.
expert PID is set. Setting 1.00 for SF makes overshoot minimum.	©
When SF=OFF is selected, expert PID does not function and ordinary PID action is carried out.	1-17 Output 2 lower limit output limiter setting screen
This screen is not displayed when P=OFF is selected.	D_L Z Initial value: 0.0
1-8 Output 1 lower limit output limiter setting screen	Setting range: 0.0 ~ 99.9% A lower limit value of control output 2 is set.
nitial value: 0.0	©
Setting range: 0.0 ~ 99.9% A lower limit value of control output 1 is set.	1-18 Output 2 higher limit output limiter setting screen
For output limiter, refer to Section 6-6.	
	/DDD Setting range: o_L2+0.1 ~ 100.0% A higher limit value of control output 2 is set.
1-9 Output 1 higher limit output limiter setting screen	©
1-9 ↓ Output 1 higher limit output limiter setting screen D	440
Setting range. o_L1+0.1 ~ 100.0% A higher limit value of control output 1 is set.	1-19 ↓ Output 2 proportional cycle time setting screen
	SSR drive voltage output: 3 seconds Setting range: 1 ~ 120 seconds.
	Proportional cycling time of control output 2 is set.
©	©
To the 1-10 screen	To the 1-20 screen

(3) Setting of Event Please refer to section 6-1, 6-2 and 6-3. 1-20 Event 1 type code setting screen Initial value: Hd Setting range: OFF, Hd, Ld, od, id, HA, LA, So, Hb E 1_5 Hď The type of event to be selected as event 1 is selected from the following code table. Table of Event Type (Alarm Type) Codes Code Type of event Remarks No selection 0 HdHigher limit deviation Initial value of event 1 Ld Lower limit deviation Initial value of event 2 oď Outside higher/lower limit deviation Within higher/lower limit deviations Ξď HR Higher limit absolute value LR Lower limit absolute value <u>50</u> Scaleover Standby action is invalid. HЬ Heater break/loop alarm Displayed only when the option is added. Event 1 hysteresis setting screen E 1_d Initial value: 5 units Setting range: 1 ~ 999 units 0.5 ON-OFF hysteresis is set for event 1. This screen is displayed when an alarm type eode is selected from Hd, Ld, od, Ed, HR, LR. 0 1-22 Event 1 standby action code setting screen E /_ [Initial value: Setting range: 1, 2, 3, 4 An event 1 standby action type code is selected from the following table This screen is displayed when an alarm type code is selected from $\mathcal{H}\mathcal{O}$, $\mathcal{L}\mathcal{O}$, $\mathcal{O}\mathcal{O}$, $\mathcal{L}\mathcal{O}$, $\mathcal{H}\mathcal{R}$, $\mathcal{L}\mathcal{R}$. 0 Table of Standby Action Codes Code Description Without standby function 2 Standby action only when power is applied. Stand-by action when power is applied and when SV in execution is changed. Control mode (without standby) 1-23 Event 2 type code setting screen Initial value: Ld Setting range: OFF, Hd, Ld, od, id, HA, LA, So, Hb Lơ The type of alarm to be selected as event 2 is selected from the table of codes. 0 1-24 Event 2 hysteresis setting screen E2_d Initial value: 5 units Setting range: 1 ~ 999 units Ω5 ON-OFF hysteresis is set for event 2. This screen is displayed when an alarm type code is selected from Rd, Ld. od, Ed. RR, LR. (C) 1-25 Event 2 standby action code setting screen E2 Initial value; Setting range: 1, 2, 3, 4 An event 2 standby action type code is selected from the following table. 0

To the 1-26 screen

(4) Heater Current Monitor Screen 1-26 Heater current monitor screen This screen is displayed when the optional heater break/loop alarm :46 R function is added and used to monitor heater current. (There is no ΙΩΟ item to be set on this screen.) Heater break/loop alarm works on output 1 Heater break/loop alarm is selectable as event 1 or event 2. Heater break/loop alarm is assignable in case output 1 is of 0 contact or SSR drive voltage. As this screen is for monitoring only, auto return does not function. (5) Setting of Heater Break/Loop Alarm 1-27 Heater break/loop alarm action setting screen 85_ñ Initial value: 💪 🕳 Setting range: Lc, -E ۲۲ output, the alarm output is maintained until OFF is selected on the heater break or loop alarm value setting screen or the power supply is cut. (C) F(Real mode): An alarm is turned ON or OFF according to a rise or fall of the value of current from a value. The hysteresis for the release of alarm output is fixed to 0.2A. 1-28 Heater break/loop standby action setting screen 46_<u>L</u> Initial value: OFF Setting range: OFF, ON off When ON is set, alarm output is withheld or kept to be on standby until the current value enters its normal range once even if the current at the time of applying power is such that an alarm should (C) 1-29 Heater break alarm value setting screen Hb. Initial value: OFF 5 Setting range: OFF, 0.1 ~ 50.0A off Heater current is detected by CT while control output is ON. Lower current than a set value of current is taken as abnormal and an alarm is output, (C) Heater loop alarm value setting screen 1-30 Initial value: OFF 5 HL Setting range: OFF, 0.1 ~ 50.0A off Heater current is detected by Cf while control output is OFF. Higher current than a set value of current is taken as abnormal and an alarm is output. 0 (6) Setting of Analog Output Type 1-31 Analog output type setting screen $Ro_{-}\tilde{n}$ Initial value: PB Setting range: *PB*, *SB*, *auE* 1, *auE2* An item intended to be output as an analog signal is selected from 4 items: Measured value (PV), target set value (SV), control output 1 (OUT1) and control output 2 (OUT2). (C) 1-32 Analog output scaling lower limit setting screen 8<u>0.</u> Initial value: 0.0 (The lower limit value of setting range for PV and SV and 0.0 for OUT1 and OUT2.) aaSetting range: Within measuring range when PV or SV is selected 0.0 ~ 100.0% when OUT1 or OUT2 is selected. A minimum value (0mV, 4mA or 0V) of analog output signal is set as the lower limit value of scaling for an intended output value. (C)

1-33 Analog output scaling higher limit setting screen Ro_H Initial value: 800.0 (The higher limit value of setting range for PV and SV and 100.0 for OUT1 and OUT2.) 8000 Within measuring range when PV or SV is Setting range: selected 0.0 ~ 100.0% when OUT1 or OUT2 is selected.) A maximum level (10mV, 20mA or 10V) of analog output signal 0 is set as the higher limit value of scaling for an intended output value. Inversed scaling of Ao_L>Ao_H is also possible. (H-L=±1 count or above) The following diagrams show analog output characteristics by scaling: In the case of Ao_L>Ao_H In the case of Ao L<Ao_H Analog output Analog output 100% 100% 0% 0% 0% Ao_L Ao_H 100% 0% Ao_H Ao_L 100% Scaling range Scaling range (7) Setting of Communication For the communication function, refer to the Communication Instruction Manual provided separately. 1-34 Communication mode setting screen co55 Initial value: しゅこ(local) Setting range: Loc, Loc (com) Loc Only a change from Com to Loc is possible by operating keys. Communication is enabled in the mode displayed on the bottom. 0 1-35 Communication address setting screen Addr Initial value: 1 Setting range: 1 ~ 255 A machine number is set in case two or more controllers are connected through communication. 0 1-36 Communication data format setting screen dRER Initial value: 7E1 (Data length 7 bits, even parity, stop bit 1) Setting range: 7E1, 8N1 (Data length 8 bits, non-parity, stop bit 1) 78 / A communication data format is set. 0 1-37 Start character setting screen 5-58 Initial value: 5とら Setting range: 525, 825 5E5 0 1-38 BCC operation type setting screen Initial value: 1 bcc Setting range: 1 ~ 4 An operation type for error detection BCC check is set from 1 to 4 shown in the following table: 0 Table of BCC Operation Types Type of Description Operation Add operation from start character to text end character 2's complement after add operation from start character to text end character Exclusive OR operation immediately after start character to text end character Without BCC operation

To the 1-39 screen

1-39 ↓ Cc <i>BP5</i> <i>I200</i>	Initial value: I Setting range: I A communicatio	speed setting 200 200, 2400, 4800, n speed is set but e of limitation in	9600, 19200 bp: 19200 bps is dis	splayed as
1-40 ↓ Co	ommunication delay time setting screen Initial value: 20 Setting range: 1 ~ 100 Time lag from receiving a communication command to transmission is set. Delay time = Set value × 0.512 msec			
1-41 ↓ Co 5E5 EEP	Initial value: &	EEP, -AA ng data in EEPRO	, 	
(a)	Туре	Wri	ting Process	
	EEP Writing entirely in EEPROM			
	 ── Printing entirely in RAM ── E Writing OUT1 and OUT2 in RAM and others in EEPROM 			
	LC-C Wn	ting OUTT and OU	12 m KAM and of	ners in EEPROM
	ontrol output control	Control Outp haracteristic s - R - R,	setting screen set. characteristics o	ı
	Output specification	Characteristic	OUT 1	OUT 2
	I output	RA	Heating	None
	1 output	DA	Cooling	None
	2 output	RA	Heating	Cooling
		DA	Heating	Heating
` `	Setting of Soft start setting		ne	5-9.
© FF	Soft start time for Soft start does no For details, see S	or changing outpu ot function when Section 6-10,	t gradually is set	t.
(1)	0) Setting of	SV Limiter		
1-44 S\	/ limiter lower	limit value se	tting screen	
58_L 00	Setting range: No. 10 N	ower limit value Measuring range l alue - 1 count er setting range o lower limit value	ower limit value I target value tha	~ higher limit
		rroneous setting i		and has some
1-45 S\	/ limiter highe	r limit value s	etting screen	
58_H 8000	Setting range: N	Higher limit value Measuring range l value + 1 count	ower limit value	~ higher limit
	range is used, a	er setting range of higher limit value troneous setting i	is set.	_

To the 1-46 screen

Note:

(C)

other advantageous effect.)

An SV limiter is set so as to be SV limiter lower limit value < SV limiter higher limit and priority is given to the lower limit

value. Therefore, a higher limit cannot be set at a smaller value than a lower limit value + 1 count.

(11) Setting of PV Bias Value 1-46 PV bias value setting screen PY. Initial value: 0 unit Setting range: -1999 ~ 2000 units αc This value is used to correct an input error from a sensor or the When a bias is used, control is also carried out with a corrected 0 (12) Setting of PV Filter Time PV filter time setting screen 1-47 Pb' Initial value: 0 second Setting range: 0 ~ 100 seconds In case input changes conspicuously or noise continues, PV filter is used to mitigate such undesirable effect. When 0 second is set, filter does not function. (C) (13) Setting of Measuring Range Code Measuring range code setting screen 1-48 $-R \cap C$ Initial value: Multi 05, voltage 86, current 92 Setting range: Select from the Table of Measuring Range Codes 85 in Section 5-8 Each code represents a combination of an input type and a measuring range. 0 (14) Setting of Temperature Unit Temperature unit setting screen 1-49 UnEE Initial value: 🗲 Setting range: C, F Select C ("C) or F ("F) as the unit of temperature for sensor This screen is not displayed when linear input (mV, V or mA) is 0 (15) Setting of Input Scaling 1-50 Input scaling lower limit value setting screen 5-Initial value: 0.0 Setting range: $-1999 \sim 9989$ units QΟ A lower limit value of scaling of linear input (mV, V or mA) is set. The screen is for monitoring only for scnsor input and setting is not possible. 0 1-51 Input scaling higher limit value setting screen <u>5c</u> HInitial value: 100.0 Setting range: $5c - L + 10 \sim 5c - L + 5000$ 1000 A higher limit value of scaling of linear input (mV, V or mA) is set. For sensor input, the screen is for monitoring only and setting is not possible. (C) Note: If input scaling higher/lower limits is set to make difference between the higher and lower limit values less than + 10 counts or more than +5000 counts, the higher limit value is automatically changed to make the difference +10 counts or A higher limit value which is smaller than a lower limit value + 10 counts or larger than a lower limit value + 5000 counts 1-52 Input scaling decimal point position setting screen Scap Initial value: 1 digit on the right of decimal point (0.0) Setting range: No decimal point (0) ~ 3 digits on the right of QΟ decimal point (0.000) The position of decimal point for input scaling is set. For sensor input, this screen is for monitoring only and setting is not possible. (C) ENT) + (C) From the 1-0 initial screen of the screen group 1 To the 1-0 initial screen of the screen group 1

5-8. Table of Measuring Range Codes

Select a measuring range from the following table. A change of the code will initialize all date related to the measuring range.

Table of Measuring Range Codes

		type	Code	Measuring range ('C)	Measuring range ('F)
		В *1	01	0 ~1800	0 ~ 3300
		R	02	0 ~ 1700	0 ~ 3100
		S	03	0 ~ 1700	0 ~3100
			<i>0</i> 4 · 2	-199.9 ~ 400.0	-300 ~ 750
		K	05	0.0 ~ 800.0	0 ~ 1500
	ple		05	0 ~ 1200	0 ~ 2200
	Thermocouple	E	07	0 ~ 700	0 ~1300
	herm	J	08_	0 ~ 600	0 ~1100
1	Т	T	<i>09</i> • 2	-199.9 ~ 200.0	-300 ~ 400
		N	10	0 ~ 1300	0 ~2300
		PLII *3	11	0 ~1300	0 ~ 2300
		Wre5-26*4	12	0 ~ 2300	0 ~ 4200
		U *5	/3 12	-199.9 ~ 200.0	-300 ~ 400
iput		L °5	14	0 ~ 600	0 ~1100
Multi-input			31	-200 ~ 600	-300 ~ 1100
Ϋ́	Pt100		32	-100.0 ~ 100.0	150.0 ~ 200.0
	^	,	33	-50.0 ~ 50.0	-50.0 ~ 120.0
	R.T.D.		34	0.0 ~ 200.0	0.0 ~ 400.0
	R.7		35	-200 ~ 500	-300 ~ 1000
		JPt100	38	-100.0 ~ 100.0	-150.0 ~ 200.0
		371100	37	-50.0 ~ 50.0	-50.0 ~ 120.0
			38	0.0 ~ 200.0	0.0 ~ 400.0
		−10~10mV	71		
		0~10mV	72	Initial value: 0.0 ~ 100	0.0
	ωV	0~20mV	73		ng range: -1999 ~ 9999
	Ħ	0~50mV	74	Span: 10 ~ 5000 count Position of decimal po	
		10~50mV	75	1, 2 or 3 digits on the	
\vdash		0~100mV	75		
		-I~1V	8:		
		0~1V	82	1 1	
Voltage	>	0~2V	83	Initial value: 0.0 ~ 100	0.0
Vo		0~5V	84		ng range: -1999 ~ 9999
		1~5V	85	Span: 10 ~ 5000 count Position of decimal po	
_		0~10V	85	1, 2 or 3 digits on the	
Current	μA	0~20mA	91		
೦	Ε.	4~20mA	92		

Thermocouple B, R, S, K, E, J, T, N: JIS/IEC

Pt100: JIS/IEC

JPt100: Former JIS

*1 Thermocouple B: Accuracy guarantee not applicable to 400°C (752°F) and below.

K, T, U: Accuracy of those whose readings are below -100°C is *2 Thermocouple

±0.7% FS

*3 Thermocouple PLII: Platinel

*4 Thermocouple Wre5-26: A product of Hoskins

*5 Thermocouple U, L: DIN 43710

NOTE: Unless otherwise specified, the measuring range will be set as listed below during the shipment from the factory

Input	Specification/Rating	Measuring range
Multi-input	K thermocouple	0.0 ~ 800.0°C
Voltage (V)	0 ~ 10V DC	0.0 ~ 100.0
Current (mA)	4 ~ 20mA DC	0.0~100.0

6. Explanation of Functions

(All the details sre mentioned here except the explanation of 5-5. Procedure of setting screen group 0)

6-1. Events

1) Deviation Alarm

An alarm action point is set by a deviation from target set value (SV). For example, when the target set value is 20°C, +10°C should be set for higher limit deviation alarm in order to put an alarm in action at 30°C and higher. To put an alarm in action at 30°C and lower when the target set value is 100°C, -70°C should be set for higher limit deviation alarm. Higher limit deviation alarm must be higher than the target set value and lower limit deviation alarm must be lower than the target set value. This is conveniently used to make the alarm action point follow deviation from the target set value. The set range will be -1999~2000 unit.

2) Absolute Value Alarm

An alarm action point is set by an absolute value. For example, when the target set value is 20°C, 30°C should be set for higher limit absolute alarm in order to put an alarm in action at 30°C and higher. To put an alarm in action at 30°C and lower when the target set value is 100°C, 30°C should be set for lower limit absolute alarm. Both higher limit and lower limit can be set at any value within the measuring range.

This alarm is convenient when the alarm action point is fixed.

Standby Action

This is used to withhold alarm action even when an alarm action point is reached when power is applied and to put the alarm in action on the alarm action point after a target set value (SV) is reached.

If an alarm action point is reached when power is applied, an alarm is output. This is used to output an alarm whenever an alarm action point is reached.


6-2. Setting of Event Standby Action


In the 1-22 event 1 standby action code setting screen in the explanation of the screen group 1:

- 1) Select a code from 1, 2 and 3 of the standby action code table when event output is used as an alarm;
- 2) Select 4 when event output is used for control. Note, however, that setting 4 will turn event output OFF if input goes out of
- When 2 is set, the standby function is put in action only when power is applied;
- When 3 is set, the standby function is put in action when power is applied and when SV in execution is changed.
- A change to 1 or 4 while standby action is in execution, the standby action will be released immediately;
- 6) If a PV value is out of a range in which an event action is ON, standby action becomes invalid even when 2 or 3 has been set for standby action. The 1-25 event 2 standby action code setting screen is the same.


6-3. Alarm Action Diagrams

The following are diagrams showing alarm actions that can be selected as event 1 and event 2.






ட் d' : Lower limit deviation alarm



ם ב': Outside higher/lower limit deviations alarm



_ d': Within higher/lower limit deviations alarm



⊢戸: Higher limit absolute value alarm



∠ R : Lower limit absolute value alarm



5 a : Scaleover



6-4. P.I.D.

1) P (Proportional action)

A percentage at which control output varies with respect to a measuring range is set. Control output increases or decreases in proportion to a difference between PV and SV values. The narrower the proportional band, the more conspicuously output changes to strengthen proportional action. If it is too narrow, however, the result of control will be close to ON-OFF action.

2) I (Integral time)

This is the function to correct an offset (constant deviation). The longer the integral time, the weaker the corrective action and the shorter the time the stronger the action but control result may be undulated due to integral hunting.

3) D (Derivative time)

This is the function to estimate a change in control output, suppress overshoot caused by integration and improve control stability. The longer the derivative time, the stronger the derivative action but control result may be vibratile.

6-5. Manual Reset

In PID action, an offset is corrected automatically by I, i.e., integration. When OFF is set for I, correction is not carried out and so output should be increased or decreased manually. This method is called manual reset.

6-6. Lower Limit and Higher Limit Setting Limiters

- Output limiter means to limit a minimum or maximum value of control output and this function is effective in maintaining the lowest temperature or suppressing overshooting of control.
- 2) Output limiter gives preference to a lower limit value. When a larger lower limit value than a higher limit value is set, the higher limit value is automatically changed to the lower limit value + 1%. In other words, it is not possible to set a higher limit value which is less than a lower limit + 1%.

6-7. Proportional Cycling Time

It should be within a range from 1~120 seconds in the case of contact output or SSR drive voltage output. Proportional cycling time is ON time + OFF time within a proportional band.

6-8. Auto Return Function

If no key is operated for 3 minutes or longer on a screen (except the 0-1 output 1 monitor screen, 0-2 output 2 monitor screen and 1-26 heater current monitor screen), the screen automatically changes to the 0-0 basic screen of the mode 0 screen group. This is called auto return.

6-9. Control Output Characteristics


1) One output

For heating action, RA (reverse action) OUT 1 is set, and for cooling action DA (direct action) OUT 1 is set.

2) Two outputs

- (1) RA (reverse action) is set for heating action OUT1 and cooling action OUT2.
- ② DA (direct action) is set for heating action OUT1 and heating action OUT2.

Control output characteristics with two outputs are shown in the following diagrams. ① shows heating and cooling control and ② two-stage heating control.



6-10. Soft Start

It is the function to raise control output gradually in a set time upon applying power and at the time of return from scaleover to normal. The function effectively prevents excess current from being present in a heater or the like.

- I) The soft start function is put in action in the following conditions:
 - When power is applied in the automatic output mode and when a normal state is returned from scaleover.
 - ② When P (proportional band) is not OFF.
 - ③ When soft start time has been set, i.e., not OFF.
- 2) Soft start is released in the following conditions:
 - 1 Soft start time has elapsed normally.
 - ② An output value under soft start control exceeds an PID operated output value.
 - 3 Soft start time is turned OFF by key operation.
 - The automatic output mode is changed to the manual output mode by key operation.
 - (5) AT (auto tuning) is executed by key operation.
 - (6) The setting of P (proportional band) is changed to OFF by key operation.
 - 7 The measuring range of input is changed by key operation.
 - ® A control output characteristic is changed by key operation.

7. Maintenance and Troubleshooting

7-1. Procedure of Maintenance Replacement and Matters to Be Attended to (Steps for replacing defective items)

① Confirmation of Model Code:

Check the model code of the component part in trouble. (Open the control box, and you can find an appropriate code in the model label affixed to the instrument case.)

② Inquiry on Input Data:

Ask the manufacturer if input data (control date of external operation, event output, set value of position, etc. at the time when an error occurs) is necessary or not.

③ Confirmation of Present Wiring Condition:

Check and record the present wiring condition. Please note that in case input data is necessary for control, the same control operation as before is not possible with a replaced product unless such data is input.

① Confirmation of Present Input Data:

When data is not known, call the input date for the product, check and record it. In case input data is required, the same control operation as before is not possible with a replaced product unless such data is input.

(5) Repair of Present Product or Procurement of New Product:

In case the product in trouble is removable from the site of installation, remove and have it repaired. If it is not possible, arrange to acquire a new product for replacement.

Setting before Starting Operation:

When replaced by a new product, check the wiring, apply power and set items as described in 5-4. Before Starting Up.

7-2. Cause of Trouble and Troubleshooting

Problem	Cause	Remedy
① Error code is displayed.	Refer to "Error Codes, Causes and Remedies."	Refer to "Error Codes, Causes and Remedies."
② Displayed PV value seems to be incorrect.	Set measuring range code is different from that of input sensor/input signal. Erroneous wiring to input terminals of sensor	 ① Check if set measuring range code is correct for input signal. ② Correct wiring to input terminals of sensor.
③ Display on the front panel goes out and the instrument does not operate.	Problem with power supply and wiring connection. Deterioration of the product.	 Inspect portions related to power source and wire connection. Check wiring. Examine the product and repair or replace.
Key unable to be operated.	Keylock is in effect. Deterioration of the product. In case communication function is added, the communication mode (Com) has been set.	Release keylock. Examine and repair or replace the product. Change the communication setting to the local mode (Loc).
⑤ ON-OFF action of control output is too fast.	ON-OFF is set for P of PID. Too small a value set for hysteresis of ON-OFF action.	Change the OFF set for P to two-position type ON-OFF action. Increase the hysteresis value of ON-OFF action.

7-3. Error Codes, Causes and Remedies

(1) Input measured value problems

Screen display	Problem	Cause	Remedy
HHHH)	Higher limit side scalcover	A break of thermocouple input wiring A break of R.T.D. input A wiring Input measured value exceeded higher limit of measuring range by 10%.	 Check thermocouple input wiring for a possible break. Check R.T.D. input A wiring for a possible break. If wiring has no problem, replace R.T.D. For voltage or current input, check the transmitting unit of measured values. Check if set code of measuring range is correct for input signal.
(LLLL)	Lower limit side scale over	Input measured value fell from lower limit of measuring range by 10%.	Check wiring of inversed polarity for measured value input.
<i>b</i> (b−−−)	A break of R.T.D. input wiring.	① A break of B② Breaks of ABB	Check R.T.D. input terminals A, B and B for breaks. If wiring has no problem, replace R.T.D.
<i>[∐HH</i> (CJHH)	Higher limit side scaleover of reference contact (CJ) of thermocouple input.	Ambient temperature of the product has exceeded 80°C.	Reduce ambient temperature to the level provided in the environment conditions for the product. In case ambient temperature has not exceeded 80°C, examine the SR90.
CJLL)	Lower limit side scaleover of reference contact (CJ) of thermocouple input.	Ambient temperature of the product has fallen to -20°C or lower.	 Raise ambient temperature to the level provided in the environment conditions for the product. In case ambient temperature has not fallen to -20°C, examine the product.

(2) Heater break/loop alarm problems

Screen display	Problem	Cause	Remedy
<i>НЬНН</i> (НВНН)	Input value from heater current detector has exceeded 55.0A.	Excess current	Reduce the current. Examine the product.
HBLL)	Input value from heater current detector fails to reached 5.0A.	The product in trouble	Examine, repair or replace the product.

8. Record of Parameter Setting (For convenience sake, recording set values and selected items is recommended.) The initial values are of Code 05 (K).

creen No.	Parameter (Item)/scree		Initial value	Setting/Selection	Record
0-0	Basic screen	0 (2)	0		
0-1	Output I monitor				-1
0-2	Output 2 monitor				
0-3	AT action	At. (<i>유</i> 上)	oFF		
0-4	Event I set value setting	EIHd.(<i>E 1Hd</i>)	2000 units		
0-5	Event 2 set value setting	E2Hd.(<i>E2Hd</i>)	1999 units		
0-6	Set value bias setting	Sb. (5b)	0 units		
1-0	Initial screen	PArA. (<i>PR-R</i>)	SEŁ		
1-1	Keylock setting	KLe. (<i>PL_</i>)	oFF		
1-2	Output I proportional band setting	P. (P)	30	-	
1-3	Output 1 hysteresis	dF. (dF)	20 units		
1-4	Output 1 integral time	I. (/)	120	-	
1-5	Output I derivative time	d. (a')	30		
1-6	Output I manual reset	mr. (<u>a</u> c)	20		
1-7	Output 1 translativeset Output 1 target value function	SF. (<i>SF</i>)	0.40		
1-8	Output 1 lower limit output limiter				
		o-L. (<u>p_L</u>)	20		
1-9	Output I higher limit output limiter	o-H. (p_H)	1000		
1-10	Output 1 proportional cycling time	o-C. (a_E)	Y: 30, P: 3		
1-11	Output 2 proportional band setting	P2. (<i>P2</i>)	30		
1-12	Output 2 hysteresis	dF2. (♂F♂)	20 units		
1-13	Output 2 integral time	12. (5)	120		
1-14	Output 2 derivative time	d2. (<i>占</i> と)	30		
1-15	Output dead band	db2. (<i>占占己</i>)	0 units		
1-16	Output 2 target value function	SF2. (<i>5F2</i>)	0.40		
1-17	Output 2 lower limit output limiter	o-L2. (a_L2)	QC .		
1-18	Output 2 higher limit output limiter	o-H2. (a_H2)	1000		
1-19	Output 2 proportional cycling time	o-C2. (@	Y: 30, P: 3		
1-20	Event I type	El-m. (<i>E 1</i> _ <u>n</u>)	Ho'		
1-21	Event 1 hysteresis	El-d. (<i>E I_d</i>)	5 units		
1-22	Event I standby action	El-i. (<i>E I</i>)	/		
1-23	Event 2 type	E2-m. (<i>E2_ā</i>)	Ld		
1-24	Event 2 hysteresis	E2-d. (<i>E2_d</i>)	5 units		
1-25	Event 2 standby action	E2-i. (<i>E2</i>)	3 tilits /		
1-26	Heater current monitor				
		Hb-A. (<i>Hb_R</i>)	,		
1-27	Heater break/loop alarm	Hb-m. (<i>Hb_</i> $\bar{\alpha}$)	LC		
1-28	Heater break/loop alarm standby	НЬ-і. (<i>НЬ_С</i>)	oFF		
1-29	Heater break alarm value	Hb-S. (<i>НЬ_5</i>)	oFF		
1-30	Heater loop alarm value	HL-S. (<i>HL_5</i>)	oFF		
1-31	Analog output type	Ao-m. (<i>Ro_ā</i>)	PB		
1-32	Analog output sealing lower limit	Ao-L. (<i>Ao_L</i>)			
1-33	Analog output scaling higher limit	Ао-Н. (<i>Яо_Н</i>)	8000		
1-34	Communication mode setting	comm.(<u>coāā</u>)	Loc		
1-35	Communication address	Addr. (<i>Pad-</i>)	1		
1-36	Communication data format	dAtA. (dRER)	ne i	100	
1-37	Start character	SchA. (5chA)	SE'S		
1-38	BCC operation type	bcc. (bcc)	,		
1-39	Communication speed	bPS. (<i>bPS</i>)	1200		
1-40	Communication delay time	dely. (<i>d'EL'S</i>)	20		
1-41	Communication memory mode	mem. (<u>AEA</u>)		-	
1-42			<i>EEP</i>		
4	Control output characteristic	Act. (A_E)	<u>r</u> R		
1-43	Soft start time	Soft. (50F≿)	oFF		
1-44	SV limiter lower limit value	SV-L. (58_L)	222		
1-45	SV limiter higher limit value	SV-H. (5B_H)	8000		
1-46	PV bias value	PV-b. (<i>РВ_Б</i>)	0 units		
1-47	PV filter time	PV-F. (<i>PB_F</i>)	<i>D</i>		
1-48	Measuring range codes Multi:	rAnG. (¬P¬G)	05 86 92		
	V:	rAnG. (-8-5)	85		
	A:	rAnG. (ア タロじ)	75'		_
1.40	T	11 12 / 11 -1 5			
1-49	Temperature unit	Unit. (LINEE)	<u>-</u>		
1-49 1-50 1-51	Temperature unit Input scaling lower limit Input scaling higher limit	Unit. (<i>LInEE</i>) Sc-L. (<i>Sc_L</i>) Sc-H. (<i>Sc_H</i>)	20 8000		

9. Specifications

l Display		RA (revers	se characteristic): Heating action (OUTI)
Digital display:	Measured value (PV)/7 segments red LED	and co	poling action (OUT2)
	4 digits		characteristic): 2-stage heating action
	Target set value (SV)/7 segments green	 Type of control/rating; 	Contact/1 a 240V AC 2A (resistive load)
Display accuracy:	LED 4 digits ±(0.3%FS + 1 digit)	(Common to Output Land 2):	1.2A (inductive load) SSR drive voltage/12V::1.5V DC
Display accuracy.	Excluding reference contact temperature	(Common to Output 1 and 2).	(Maximum load current 30mA)
	compensation accuracy of thermocouple		Current/4~20mA DC (Maximum load
	input.		resistance 600Ω)
	Accuracy of readings lower than -100°C of		Voltage/0~10V DC (Maximum load
	thermocouples K, T, U inputs is ±0.7%FS. Accuracy guarantee not applicable to	 Control output resolution: 	current 2mA) Control output 1: approx. 0.0125% (1/8000)
	400°C (752°F) and below of B	Control output resolution.	Control output 2: approx. 0.5% (1/200)
	thermocouple.	 Control output ! 	como ouque si approvi ois it (ii soo)
Display accuracy maintaining	ng range:	Proportional band (P):	OFF, 0.1~999.9% (ON-OFF action by OFF
	23°C ± 5°C (18~28°C)	Integral time (I):	OFF, 1~6000 seconds
Display resolution:	Differs by measuring range (0.001, 0.01,	Devicesting time (D):	(P or PD action by OFF)
Measured value dienlay range:	0.1 and 1) -10%~110% of measuring range	Derivative time (D):	OFF, 1~3600 seconds (P or PI action by OFF)
Display updating cycle:	0.25 seconds	Target value function:	OFF, 0.01~1.00
Action display/color:	7 type, LED lamp display	ON-OFF hysteresis:	1~999 units (Effective when P=OFF)
	Control output (OUT1, OUT2)/Green	Manual reset:	-50.0~50.0% (Effective when I=OFF)
	Event (EVI, EV2)/Orange	Higher/lower limit output limiter:	Lower limit 0.0~99.9%, higher limit
	Auto tuning/Green		0.1~100.0% (Lower limit value < Higher limit value)
	Manual control output (MAN)/Green Set value bias, communication	Proportional cycle:	Imit value) I~120 seconds (for contact and SSR drive
	(SB/COM)/Green	r roportional cycle.	voltage output)
Setting	\	 Control output 2 (option) 	G
Setting method:	By operating 4 keys (, , , ,	Proportional band (P):	OFF, 0.1~999.9%
	and (ENT) on the front panel		(ON-OFF action by OFF)
Target value setting range:	Same as measuring range (within setting	Integral time (I):	OFF, 1~6000 seconds
	limiter)	Desirative time (D):	(P or PD action by OFF) OFF, 1~3600 seconds
Setting limiter:	Individual setting for higher and lower	Derivative time (D):	(P or PI action by OFF)
	limits, any value is selectable within measuring range (Lower limit	Target value function:	OFF, 0.01~1.00
	value <higher limit="" td="" value)<=""><td>ON-OFF hysteresis:</td><td>1~999 units (Effective when P=OFF)</td></higher>	ON-OFF hysteresis:	1~999 units (Effective when P=OFF)
I Input	value inglier milit value)	Dead band:	-1999~5000 units (Overlap with a negative
Type of input:	Selectable from multiple (TC, Pt, mV),		value)
	voltage (V) and current (mA)	Higher/lower limit output limiter:	Lower limit 0.0~99.9%, higher limit
Thermocouple:	B, R, S, K, E, J, T, N, PL II, Wre5-26 (UL		0.1~100.0% (Lower limit value < Higher limit value)
Innut impadance:	(DIN 43710)) 500kΩ minimum	Proportional cycle:	1~120 seconds (for contact and SSR drive
Input impedance: External resistance tolerance:	below 100Ω		voltage output)
Burnout function:	Standard feature (up scale)	 Manual control 	
Reference contact compens		Output setting range:	0.0~100.0%
	± 1°C (within the accuracy maintaining	Setting resolution:	0.1% Balanceless bumpless (within proportional
	range $(23 \pm 5^{\circ}C)$)	Manual Addo switching.	range, however.)
	± 2°C (between 5 and 45°C of ambient temperature)	 Soft start: 	OFF, 1~100 seconds
R,T.D.:	Pt100/JPt100, 3-wire type	AT point:	SV value in execution
Normal current:	0.25 mA	 Control output characteristic: 	RA (reverse characteristic)/DA (direct
Lead wire tolerance:	5Ω maximum/wire (3 lead wires should	* 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	characteristic) switching by front key
	have the same resistance.)	Isolation:	Contact output isolated from all.
Voltage mV:	-10~10, 0~10, 0~20, 0~50, 10~50,		Analog output not insulated from SSR driv voltage, current and voltage but insulated
V:	0~100mv DC		from others. (In case another output is also
Input impedance:	-I~I, 0~I, 0~2, 0~5, I~5, 0~10V over 500kΩ		of SSR drive voltage, current or voltage,
Current mA:	0~20, 4~20mA DC		however, two outputs are not insulated fro
Receiving impedance:	250Ω		each other.)
Input scaling function:	Scaling possible for voltage (mV, V) or	■ Event output (option)	2 mainta of EVI and EV2
G. F.	current (mA) input	Number of event points:Types:	2 points of EV1 and EV2 Selectable from the following 9 types for
Scaling range:	-1999~9999 counts		EVI and EV2:
Span: Position of decimal point:	10~5000 counts None, 1, 2 and 3 digits on the right of	oFF:	No selection
. Johnson of decimal public.	decimal point	Hd:	Higher limit deviation
•	P		Lower limit deviation
·	0.25 seconds		
Sampling cycle: PV bias:	0.25 seconds -1999~2000 units		Outside higher/lower limit deviations
Sampling cycle: PV bias: PV filter:	-1999~2000 units 0~100 seconds		Within higher/lower limit deviations
Sampling cycle: PV bias: PV filter:	-1999~2000 units 0~100 seconds Control input not insulated from system, set	ਹਰ: ਮੁਲ	: Within higher/lower limit deviations : Higher limit absolute value
Sampling cycle: PV bias: PV filter:	-1999~2000 units 0~100 seconds Control input not insulated from system, set value bias, and CT input but insulated from	ਹਰ: ਮਸ: Lਸ:	Within higher/lower limit deviations Higher limit absolute value Lower limit absolute value
Sampling cycle: PV bias: PV filter: Isolation:	-1999~2000 units 0~100 seconds Control input not insulated from system, set	Ед: НЯ: 1.8: 5a:	: Within higher/lower limit deviations : Higher limit absolute value
Sampling cycle: PV bias: PV filter: Isolation:	-1999~2000 units 0~100 seconds Control input not insulated from system, set value bias, and CT input but insulated from	Ед: НЯ: 1.8: 5a:	Within higher/lower limit deviations Higher limit absolute value Lower limit absolute value Scaleover
Sampling cycle: PV bias: PV filter: Isolation: Control Control mode	-1999~2000 units 0~100 seconds Control input not insulated from system, set value bias, and CT input but insulated from	Сд: НЯ: L Я: 5 о: Нь:	Within higher/lower limit deviations Higher limit absolute value Lower limit absolute value Scaleover Heater break/loop alarm Absolute values (both higher limit and lower limit): Within measuring range
Sampling cycle: PV bias: PV filter: Isolation: Control Control mode With I output: Expert PII RA (reverse	-1999~2000 units 0~100 seconds Control input not insulated from system, set value bias, and CT input but insulated from others Denotrol with auto tuning function se characteristic): Heating action	Сд: НЯ: L Я: 5 о: Нь:	Within higher/lower limit deviations Higher limit absolute value Lower limit absolute value Scaleover Heater break/loop alarm Absolute values (both higher limit and lower limit): Within measuring range Deviations (both higher limit and lower
Sampling cycle: PV bias: PV filter: Isolation: Control Control With I output: RA (reversible (reversible) A (direct	-1999~2000 units 0~100 seconds Control input not insulated from system, set value bias, and CT input but insulated from others D control with auto tuning function se characteristic): Heating action the characteristic): Cooling action	Сд: НЯ: L Я: 5 о: Нь:	Within higher/lower limit deviations Higher limit absolute value Lower limit absolute value Scaleover Heater break/loop alarm Absolute values (both higher limit and lower limit): Within measuring range Deviations (both higher limit and lower limit): —1999~2000 units
Sampling cycle: PV bias: PV filter: Isolation: Control Control With I output: RA (reversible (reversible) A (direct	-1999~2000 units 0~100 seconds Control input not insulated from system, set value bias, and CT input but insulated from others D control with auto tuning function se characteristic): Heating action to characteristic): Cooling action D control with auto tuning function +	Сд: НЯ: L Я: 5 о: Нь:	Within higher/lower limit deviations Higher limit absolute value Lower limit absolute value Scaleover Heater break/loop alarm Absolute values (both higher limit and lower limit): Within measuring range Deviations (both higher limit and lower

1~999 units ■ Analog output (option) Hysteresis: Selectable from the following 4 types for Standby action: Number of output points: I point EV1 and EV2: I Without standby action. Type of analog output: Selectable from measured value, target 2 Standby when power is applied. value (SV in execution), control output 1 3 Standby when power is applied and when SV value in execution is changed. and control output 2. 4~20mA DC/Maximum load resistance 300Ω Output signal/rating: 4 Control mode without standby action (No 0~10V DC/Maximum load current 2mA alarm is output at the time of abnormal $0{\sim}10 mV$ DC/Output impedance 10Ω input). Output scaling: Measured value, target value: Within Contact (1a × 2 points common)/240V AC Output type/rating: measuring range (inversed scaling possible) Control output I and 2 0.0~100.0% 1A (resistive load) Output updating cycle: 0.25 seconds (inversed scaling possible) Heater break/heater loop alarm (option)
Break/loop detection only for OUT1 (Selectable when output type is ±0.3% FS (with respect to displayed value) Output accuracy: Output resolution: About 0.01% (1/10000) contact or SSR drive voltage) Output updating cycle: 0.25 seconds 30A, 50A to be designated when CT is Current capacity: Isolation: Analog output insulated from system and ordered. inputs but not insulated from control output Heater current is detected by external CT Alarm action: except contact output. ■ General specifications provided as an accessory. Non-volatile memory (EEPROM) When heater break is detected while control Data storage: • Environmental conditions for instrument operation:
Temperature: -10~50°C output is ON=Alarm output ON When heater loop alarm is detected while control output is OFF=Alarm output ON 90% RH or less (no dew condensation) Humidity: OFF, 0.1~50.0A (Alarm action is stopped · Current setting range: 2000m from the sea level or lower Height: by setting OFF) Category: Η Degree of pollution: Setting resolution: 0.1A Current display range: 0.0~55.0A -20~65°C Storage temperature: Display accuracy: ±2.0A (Sine wave at 50Hz) Supply voltage: Either 100-240V AC±10% 50/60Hz or Minimum time to identify action: 24V AC/DC±10% to be designated. 0.25 seconds (every 0.5 seconds) common to ON and OFF SR91: 100-240VAC 11VA maximum for Power consumption: AC; 6W for DC 24V; 7VA for AC 24V SR92, SR93 and SR94: 100-240VAC Alarm retention mode: Selectable from lock (to retain) and real (not to retain). Selectable from without (OFF) and with 15VA maximum for AC; 8W for DC Standby action: (ON). 24V; 9VA for AC 24V 0.5 seconds 50 dB or higher in normal mode (50/60 Hz) Sampling cycle: Input/noise removal ratio: CT input not insulated from system and 130 dB or higher in common mode Isolation: other inputs but insulated from the rest. (50/60 Hz) Safety: IEC1010 and EN61010-1 ■ Set value bias (option) Conformity with standards: -1999~5000 units EMC: EN61326 Setting range: No-voltage contact or open collector (level Insulation resistance: Between input/output terminals and power terminal 500V DC 20M Ω or above; Action input: action) about 5V DC, ImA maximum · Minimum level retention time: 0.15 seconds Between input/output terminals and Isolation: Action input not insulated from system and protective conductor terminal 500V DC other inputs but insulated from others $20M\Omega$ or above ■ Communication function (option) Between input/output terminals and power · Dielectric strength: RS-232C, RS-485 terminal 2300V AC/minute; Between Type of communication: RS-232C 3-line type half duplex system Communication system: power terminal and protective conductor RS-485 2-line type half duplex system terminal 1500V AC/minute (RS-485 is of half-duplex multi-drop (bus) Protective structure: Only front panel has dust-proof and dripproof structure equivalent to IP66. Start-stop synchronization system Synchronization system: Material of case: PPO resin molding (equivalent to UL94V-I) RS-232C The longest: 15 m Communication distance: RS-485 The longest 500 m (depending on External dimensions: SR91: H48 × W48 × D111 (Panel depth: 100) mm Communication speed: 1200, 2400, 4800, 9600, 19200 bps SR92: H72 × W72 × D111 (Panel depth: 100) mm 7 bits, even parity, 1 stop bit or SR93: H96 × W96 × D111 (Panel depth: 100) mm Data format: 8 bits, non-parity, 1 stop bit SR94: H96 × W48 × D111 (Panel depth: 100) mm Communication address: 1~255 • Mounting: Push-in panel (one-touch mount) Communication memory mode: EEP/RAM/r_E Panel thickness: 1.0~4.0 mm Communication BCC: Add/Add two' S cmp/XOR/None SR91: H45 × W45 mm Panel cutout: Communication delay time: 1~100 (× 0.512 msec) SR92: H68 × W68 mm Communication code: ASCII code SR93: H92 × W92 mm Communication protocol: Shimaden's standard protocol SR94: H92 × W45 mm Number of connectable instruments: Weight: SR91: Approximately 170 g RS-232 1 SR92: Approximately 280 g RS-485 up to 31 SR93: Approximately 330 g

SR94: Approximately 240 g

Isolation:

Communication signals insulated from

system, each input and each output.